



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

February 20, 2013

Samuel Campbell, III
Department Head, Safety Engineering and ITS
Rolls-Royce Motor Cars, Ltd.
BMW of North America, LLC
200 Chesnut Ridge Rd. (Bldg. 150)
Woodcliff Lake, NJ 07677

NVS-215KS
13V-047

Subject: Fuel Filler Neck Anti-Misfueling Device Missing

Dear Samuel Campbell, III:

This letter serves to acknowledge Rolls-Royce Motor Cars, Ltd.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
ROLLS-ROYCE/PHANTOM/2013

Mfr's Report Date: February 7, 2013

NHTSA Campaign Number: 13V-047

Components:
FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY:FILLER PIPE AND CAP

Potential Number of Units Affected: 27

Problem Description:
Rolls-Royce Motor Cars is recalling certain model year 2013 Phantom vehicles manufactured from November 2, 2012, through January 18, 2013. The fuel filler necks may be missing the anti-misfueling devices. The devices prevent misfueling and discharge static electricity.

Consequence:
Without the anti-misfueling device, there is an increased risk of fire from static electricity.

Remedy:
Rolls-Royce is presently contacting all affected owners. Dealers will inspect the gas tank and replace any affected fuel filler necks, free of charge. The recall began in early February 2013. Owners may contact Rolls-Royce at 1-877-877-3735.

Notes:
Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "J. Timian", with a stylized flourish at the end.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement